
LABCAR-FWP V11.12.0

Release Notes

Copyright

The data in this document may not be altered or amended without special notification from ETAS GmbH. ETAS GmbH undertakes no further obligation in relation to this document. The software described in it can only be used if the customer is in possession of a general license agreement or single license. Using and copying is only allowed in concurrence with the specifications stipulated in the contract. Under no circumstances may any part of this document be copied, reproduced, transmitted, stored in a retrieval system, or translated into another language without the express written permission of ETAS GmbH. © **Copyright** 2019 ETAS GmbH, Stuttgart
The names and designations used in this document are trademarks or brands belonging to the respective owners.

Contents

1	Introduction.....	4
1.1	Definitions and Abbreviations.....	4
2	Product Definition.....	4
2.1	Functions at a glance	4
2.2	General Description	4
2.2.1	System Prerequisites.....	4
3	Changes	5
3.1	Configuration Information.....	5
3.2	Released Features.....	5
3.2.1	New or Enhanced Functions	5
3.2.2	Corrected Errors	5
3.2.3	Known Issues	5
4	Contact, Support and Problem Reporting	5

1 Introduction

1.1 Definitions and Abbreviations

Term/Abbreviation	Definition
EHI	ETAS Help Desk International
HSP	Hardware Service Pack
HSP-UT	HSP-Update Tool
HW	Hardware
KIR	Known Issue Report – For severe Problem Reports which occur after a release, ETAS has introduced the Known Issue Report to inform affected customer immediately. The current Known Issues of former versions can be found on the ETAS website: http://www.etas.com/kir
SW	Software

2 Product Definition

2.1 Functions at a glance

The **Hardware Service Pack** is a product for the firmware management on the ETAS hardware.

This product consists of two components.

- HSP Update Tool
- Service Pack
 - LABCAR Hardware (LABCAR-FWP)
 - MCD Hardware (SP)

The HSP Update Tool is the user Interface for the firmware update process. This tool enables an easy update of the firmware in the ETAS hardware and gives clear information on the current versions of the firmware contained in the hardware. The Service Pack contains the actual firmware, i.e. the files that will be downloaded to the hardware.

These release notes are valid for the HSP LABCAR Firmware Pack. The content of this release notes can also be launched for each installed HSP version in the HSP Update Tool after selecting the required LABCAR firmware Pack.

2.2 General Description

2.2.1 System Prerequisites

The following minimum system prerequisites have to be met:

HSP V11.12.0 has to be installed. See the HSP-UT release notes or Getting Started for information about the HSP installation.

3 Changes

This chapter describes changes with respect to the previous HSP versions and lists the current known issues.

3.1 Configuration Information

Configuration	Version	Release Date
LABCAR-FWP	V11.12.0	2019-03-26

3.2 Released Features

3.2.1 New or Enhanced Functions

With this release the following functionality has been added. This list also shows features of existing previous refreshes of this HSP major version.

Description	Products	Released With
-	-	-

3.2.2 Corrected Errors

The following table contains all errors that have been corrected in this and previous refresh releases.

Call ID	Description	Products	Released With
607780	Irregular state of Relais control after going offline	ES5300.1	LABCAR-FWP V11.12.0

3.2.3 2.3 Known Issues

3.2.4 Known Issues

The following table contains known problems open for this release.

Call ID	Description	Products
-	-	-

4 Contact, Support and Problem Reporting

For details of your local sales office as well as your local technical support team and product hotlines, take a look at the ETAS website:

ETAS subsidiaries WWW: www.etas.com/en/contact.php

ETAS technical support

WWW: www.etas.com/en/hotlines.php